



Quick Guide for the safe and proper operation of ESSIG Impact Moles.


TIGHTEN THE END NUT SECURELY!



CHECK THAT THE LOCKING NUT ON THE STEP NOZZLE IS TIGHT.




DOES THE REVERSING MECHANISM MOVE FREELY?




DO NOT CARRY THE MOLE BY THE HOSE!



OBSERVE THE EXISTING PIPELINE ROUTES!



CREATE A PIT TO MATCH THE MACHINE DIMENSIONS!



BLOW OUT THE 20 m HOSE BEFORE CONNECTING!



MAXIMUM OPERATING PRESSURE: 6 BAR!



ENSURE SUFFICIENT OIL IN THE LUBRICATOR!

